

The Ohio Gas Association
in conjunction with affiliate members
AEGIS Insurance Services, Inc.
and
Heath Consultants
presents

**FIRST RESPONDER / GAS
LEAK PINPOINTING TRAINING**

Monday
September 9, 2013



www.ohiogasassoc.org

An OGA OQ Tool

Ohio Gas Association
Training Center
6100 Emerald Parkway
Dublin, OH 43016

Instructors

Ron Six of AEGIS Insurance Services, Inc.
Eric Six of Heath Consultants

This program is designed to teach “first response” personnel the proper procedures which can be followed when responding to gas leaks, “dig-ins”, odor complaint calls or other possible gas related emergencies. This course covers the proper use of gas and carbon monoxide detecting instruments and suggests how to use this equipment effectively in determining if a problem exists. Hazard identification and procedures for handling gas related emergencies will also be covered along with steps to follow in pinpointing underground gas leaks. Each person in attendance will be provided with a training booklet and the AEGIS Emergency Tip Cards/Visor set.

AGENDA

8:30 a.m. Registration

Cost \$125.00

Includes continental breakfast, lunch, breaks and all materials

9:00 a.m. • Physical properties of natural gas
• Combustion chamber demonstration
• Major leakage causes & case histories

10:30 a.m. Break

10:45 a.m. • Proper use and interpretation of gas and CO detection instrument readings
• Hazard recognition
• Gas leak evaluation/Classification & MAKESAFE

11:45 a.m. Lunch

12:30 p.m. • Odor complaint investigation- receiving the call
• Odor complaint investigation - responding to the call
• Conducting the odor complaint investigation
• “Table top” mock emergency drills
• Emergency response

2:00 p.m. Break

2:15 p.m. • Pinpointing underground leaks and proper use of soil purgers/aerators

3:30 p.m. • Voluntary written exam

DIRECTIONS to the Ohio Gas Association

From the SOUTH: Take I-270 North to Exit 15, Tuttle Crossing, Turn West (LEFT) off the Ramp onto Tuttle Crossing proceed to Emerald Parkway, Turn North (RIGHT) Proceed to OGA Offices in IGS Energy Building, 6100 Emerald Parkway Dublin, OH 43016

From the North/East: Take I-270 West to Exit 17 B (Marysville Rt 161/33), Take 1st Exit West bound Avery-Muirfield, turn South (LEFT) on Avery to Sheir Rings Rd turn East (LEFT) to Emerald Parkway, turn South (RIGHT) Proceed to 6100 Emerald Parkway, Dublin, OH 43016

From the West: Take Rt 33 to Avery Rd Exit just prior to I-270 Exits, exit Avery-Murifield turn South (LEFT) on Avery to Sheir Rings Rd turn East (LEFT) to Emerald Parkway, turn (RIGHT) Proceed South (RIGHT) Proceed to 6100 Emerald Parkway, Dublin, OH 43016

